



Experiencias en la gestión de incidentes con chatarra contaminada en las industrias Españolas

Experiences in Management of incident with Contaminated Scrap Metal in Spanish Industries

February 2009

Carlos Sánchez – UNESID / Riva Group Spain

Presentation structure:

- **Case 1.-**

Contingency management of
a Cs source melting

Place: Alcalá de Guadaíra,
Sevilla (Spain)

Company: Siderúrgica
Sevillana, S. A


- **Case 2.-** Video
presentation

Contingency management
of a Cs source
fragmentation.

Place: San Andrés de los
Tacones, Gijón (Spain)

Company: Daniel González
Riestra S.L.

Evolution of detections in Siderúrgica Sevillana, S. A.



Contingency summary in Siderúrgica Sevillana, S. A. (1)

- Date: 07th December 2001
- Company subscribed to the *Protocol for Collaboration on the Radiation Monitoring of Metallic Materials*.
Compromise: operate and maintain a surveillance and control system, with Radiation Portal Monitor, spectrometric control of steel probe and specialized technical personnel.
- Source activity: Between 3 and 4 Curios (Ci) roughly.
- Total volume of generated waste: 340 m³
- For the cleanup operations it was engaged an authorized company with professional exposed personnel, supervised by a Technical Radiological Protection Unit (UTPR), according to in force regulation.
- Shutdown period for decontamination: 30 days.



Ciclo del Acero



Chatarra y parque de chatarra

Contingency summary in Siderúrgica Sevillana, S. A. (1)

- Date: 07th December 2001
- Company subscribed to the *Protocol for Collaboration on the Radiation Monitoring of Metallic Materials*.
Compromise: operate and maintain a surveillance and control system, with Radiation Portal Monitor, spectrometric control of steel probe and specialized technical personnel.
- Source activity: Between 3 and 4 Curios (Ci) roughly.
- Total volume of generated waste: 340 m³
- For the cleanup operations it was engaged an authorized company with professional exposed personnel, supervised by a Technical Radiological Protection Unit (UTPR), according to in force regulation.
- Shutdown period for decontamination: 30 days.



Contingency summary in Siderúrgica Sevillana, S. A. (2)

- Exemption limits set by the regulatory body (CSN)
 - Dose rate: 1 $\mu\text{Sv/h}$
 - Surface contamination: 4 Bq/cm^2
 - Activity concentration: 10 Bq/g
- No facility personnel contact contamination or consumption.
maximum dose per worker $\lll 1$ mSv/year .
- No atmosphere contamination.
- Contingency total accounted cost rises to 3 millions €, including facility decontamination and produced waste management.
(Activity cease cost not include)

Situation totally new and unknown to the company.
Need to make decisions very quickly about
unusual matters.

The worst time of the company's existence.
Brought about the beginning of a new era of
great improvements.

FIRST: Thanks to all the people who collaborated without a break on the resolution of the contingency.

Thanks to:

- **CSN** Nuclear Safety Council
- **ENRESA** Empresa Nacional de Residuos Radiactivos
- **PROINSA** Authorized UTPR by the CSN
- **CESPA** Qualified personnel assistance

1.- to Know what's happening, to RATIFICATE
the incident:

Needs:

- Suitable Surveillance System
- Correct Interpretation of the information
- External expert help

2.- to Know the MAGNITUDE of the incident:


- Affected areas
- To inform
- Weigh up the situation and engage the necessary resources
- Introduce protection measures
- Stop the exit of waste from the steelmaking process.

3.- to ISOLATE the affected areas to avoid unnecessary risks.

4.- Decontamination, CLEANUP in the shortest time possible.

Analisis of possible causes of the contingency on 7/12/2001

- Surveillance system failure (checked this didn't happen)
- Inadequate surveillance system (checked the suitability of the compulsory surveillance equipment)
- Not attended alarms (checked that no other alarms did occurred)
- The melting occurred during the cleanup of a scrap stock yard, therefore the source might have been at the back of the yard for an undetermined period of time.

 – Radioactive source was in the stock when the surveillance system was implemented in 1999.

Problems with the Initial Surveillance System. Evolution



- Protocol initially didn't foresee the installation of a control system for the exhaust gases in the facility. It considered detectable the Cs in the steel casting probe.
- Company installed voluntarily and in an experimental way, a exhaust gas sensor purchased in the market. The first level alarm comes fixed by the supplier in 50 mSv/h
- This sensor warned the company about the melting.
- After the event, it has been substituted by a more efficient equipment with double sensor that warns above 1 μ Sv/h.
- The spectrometric analysis in the steel probe doesn't produce a significant increase of the activity (<0,1 Bq/g).
- The surveillance system have been strengthen with a scrap redundant control during the basket charge before being moved to the furnace. Advantage: it's able to control less amount of scrap (truck <25 t, octopus crane <8t).

- Spanish Protocol has demonstrated its ability to adapt unexpected situations.
- After the experiences the compile knowledge has reduced the “unexpected” situations.
- Our company has had the ability to analyze the problematic of these inadvertent materials on equal footage with the administration, which gives a rather proactive environment.
- Spanish iron steel covered by the Protocol offers an add value due to their guaranteed radioactivity security.

Thanks for your attention

